

Article Datasheet

Art.No.: 4075

CONNECTION PARTS FOR VISORHOLDER

Article Description:

- 1 pair for visorholder
- required if no helmet ear protection is available
- suitable for helmets: 4050
- packaging unit: 10

***** matching accessories:**

Art. 4050 - forestry worker helmet set

Art. 4078- visorholder (for joint use with art. 4050)

--> Art. 4078 - visorholder is matching with art. 40891 - polycarbonat replacement screen



Catalogue Page: 473

HELMUT FELDTMANN GmbH

Zunftstraße 28 · 21244 Buchholz
Telefon 04181/2004-0 · info@feldtmann.de
Geschäftsführer: Thomas Feldtmann
www.feldtmann.de · www.elysee-workwear.com
www.optiflex-gloves.de · HR Tostedt B 204869
Steuer-Nr. 15/200/49916 · USt-IdNr. DE 114965903

Hamburger Sparkasse, Buchholz
IBAN: DE06 200 505 50 1383 126 222
SWIFT (BIC) HASPDEHHXXX
Sparkasse Harburg-Buxtehude, Buchholz
IBAN: DE75 2075 0000 0003 0361 00
SWIFT (BIC) NOLADE21HAM

Wir verkaufen und liefern ausschließlich auf Basis unserer Verkaufs- und Lieferbedingungen, die wir auf Wunsch gern zusenden. Diese sind auch im jeweils aktuellen Hauptkatalog zu finden oder auf unserer Homepage www.feldtmann.de.